



Av. Pte. Arturo Illia 6204 - Los Polvorines – Tel. 4667-4009

E-mail: info@tubocenter.com.ar – Web: www.tubocenter.com.ar

Tabla de conversión de pulgadas a milímetros

| Fracción de Pulgadas | pulgadas | mm |
|----------------------|----------|--------|
| 1/64 | 0,0156 | 0,3969 |
| 1/32 | 0,0313 | 0,7938 |
| | 0,0394 | 1,0000 |
| 3/64 | 0,0469 | 1,1906 |
| 1/16 | 0,0625 | 1,5875 |
| 5/64 | 0,0781 | 1,9844 |
| | 0,0787 | 2,0000 |
| 3/32 | 0,0938 | 2,3813 |
| 7/64 | 0,1094 | 2,7781 |
| | 0,1181 | 3,0000 |
| 1/8 | 0,1250 | 3,1750 |
| 9/64 | 0,1406 | 3,5719 |
| 5/32 | 0,1563 | 3,9688 |
| | 0,1575 | 4,0000 |
| 11/64 | 0,1719 | 4,3656 |
| 3/16 | 0,1875 | 4,7625 |
| | 0,1969 | 5,0000 |
| 13/64 | 0,2031 | 5,1594 |
| 7/32 | 0,2188 | 5,5563 |
| 15/64 | 0,2344 | 5,9531 |
| | 0,2362 | 6,0000 |
| 1/4 | 0,2500 | 6,3500 |
| 17/64 | 0,2656 | 6,7469 |
| | 0,2756 | 7,0000 |
| 9/32 | 0,2813 | 7,1438 |
| 19/64 | 0,2969 | 7,5406 |
| 5/16 | 0,3125 | 7,9375 |

| Fracción de Pulgadas | pulgadas | mm |
|----------------------|----------|---------|
| | 0,3150 | 8,0000 |
| 21/64 | 0,3281 | 8,3344 |
| 11/32 | 0,3438 | 8,7313 |
| | 0,3543 | 9,0000 |
| 23/64 | 0,3594 | 9,1281 |
| 3/8 | 0,3750 | 9,5250 |
| 25/64 | 0,3906 | 9,9219 |
| | 0,3937 | 10,0000 |
| 13/32 | 0,4063 | 10,3188 |
| 27/64 | 0,4219 | 10,7156 |
| | 0,4331 | 11,0000 |
| 7/16 | 0,4375 | 11,1125 |
| 29/64 | 0,4531 | 11,5094 |
| 15/32 | 0,4688 | 11,9063 |
| | 0,4724 | 12,0000 |
| 31/64 | 0,4844 | 12,3031 |
| 1/2 | 0,5000 | 12,7000 |
| | 0,5118 | 13,0000 |
| 33/64 | 0,5156 | 13,0969 |
| 17/32 | 0,5313 | 13,4938 |
| 35/64 | 0,5469 | 13,8906 |
| | 0,5512 | 14,0000 |
| 9/16 | 0,5625 | 14,2875 |
| 37/64 | 0,5781 | 14,6844 |
| | 0,5906 | 15,0000 |
| 19/32 | 0,5938 | 15,0813 |